

Work Order ID 68945

Tuesday, April 26, 2011 10:41:22 AM



Page 1

Item ID: D3403-1

Accept



Setup Start



Revision ID:

Stop



Item Name: Bushing

Start Date: 4/26/2011 Start Qty: 60.00



Cust Item ID:

Required Date: 5/2/2011 Req'd Qty: 60.00



Customer:

Reference:

Approvals:

Process Plan:

[Signature]

Date:

7/04/26

Tooling:

Date:

QC:

Date:

SPC (Y/N):

Date:

Run Start



Stop



Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr
D3403	C

100	Hardinge CNC LATHE SMALL	0.00							
	Hardinge	Memo							
Hardinge CNC Lathe Small	1- Turn as per Folio FA556 & Dwg D3403	Folio Rev: <i>WJL</i>							
	2-Deburr								

60 *[Signature]*

110	QC2- Inspect parts off machine FAI/FAIB	0.00							
	QC	Memo							
Quality Control									

[Signature] 11/5/08

60 *[Signature]*

120	QC8- Inspect parts - second check	0.00							
	QC	Memo							
Quality Control									

[Signature] 11/5/08

SL 11/05/09

W/O:		WORK ORDER CHANGES						
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 68945

Tuesday, April 26, 2011 10:41:22 AM



Page 2

Item ID: D3403-1

Accept



Setup Start



Revision ID:

Stop



Item Name: Bushing

Start Date: 4/26/2011 Start Qty: 60.00



Cust Item ID:

Required Date: 5/2/2011 Req'd Qty: 60.00



Customer:

Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Run Start



QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Stop



Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
130 	Identify as per dwg & Stock Location: <u>052</u>	0.00							
Packaging	Memo	0.00							
Packaging									
140 	QC21- Final Inspection - Work Order Release	0.00							
QC	Memo	0.00							
Quality Control									

11/5/09 (60)

11/5/09

MF

11-05-09

W/O:		WORK ORDER CHANGES						
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

Tuesday, April 26, 2011 10:41:29 AM

Page 1

Work Order ID: 68945

Parent Item: D3403-1

Parent Item Name: Bushing



Start Date: 4/26/2011

Required Date: 5/2/2011

Start Qty: 60.00

Required Qty: 60.00

Comments: IPP Rev:A 05.08.31 New issue KJ/JLM
IPP Rev:B 06-03-07 As per Rev B JLM

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
---------------------------------	------------------------	---------------	-------------	---------------------	------------------	-----------------	--------------------	----------------	-------------	--------------	---------------	----------------	--------

M303R0.750

Purchased

No

100

f

141.0500

0.208

12.48



303 Round Bar 0.750



SD 11/5/8

Location

Loc Qty

Loc Code

MAT028

141.05

117142

26.05

117328

55

117481

60

6 RT
7 RT

W/O:		WORK ORDER CHANGES						
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

W/O:		WORK ORDER CHANGES						
DATE	STEP	PROCEDURE CHANGE		By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector


Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)							
DATE	STEP	Description of NC Section A	Corrective Action		Section B		Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date				

NOTE: Date & initial all entries

SHOP COPY
RETURN TO
ENGINEERING
UNCONTROLLED COPY
SUBJECT TO AMENDMENT
WITHOUT NOTICE
WORK ORDER
NO. *68945*
PL1104-26



SECTION A-A

D3403-X BUSHING

DART P/N	L	WEIGHT (lbs)
D3403-1	2.416	0.07
D3403-3	2.165	0.06
D3403-5	2.500	0.07

RELEASED
2010-09-07

NOTES:

- 1) MATERIAL: AISI 303 SS ROUND BAR
PER ASTM A582
REF. DART SPEC. M303R
- 2) FINISH: NONE
- 3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) UNITS: INCHES UNLESS OTHERWISE NOTED
- 5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
- 6) IDENTIFICATION: NONE
- 7) WEIGHT: PER TABLE

C	REFORMAT TO CURRENT STD PER QSI 043; ADDED D3403-5. TOL WAS +0.005/-0.000. REASON: PAR#10-029	MB	10.04.21
B	ADD COUNTERSINK	PH	06.01.23
A	NEW ISSUE	PH	05.03.07
REV.	DESCRIPTION	BY	DATE
DESIGN		DART AEROSPACE LTD	
DRAWN		HAWKESBURY, ONTARIO, CANADA	
CHECKED		DRAWING NO.	REV. C
MFG. APPR.		D3403	SHEET 1 OF 1
APPROVED		TITLE	SCALE
DE APPR.		BUSHING	NTS
DATE	10.04.21	COPYRIGHT © 2005 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL. A NOTE SHIPPED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	

W/O:		WORK ORDER CHANGES						
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries